ITT AFO Dec No. OF 05 05 Dec. 04/00	ITT la directaire la a AEC Bratan
ITT AES Doc. No. OF-05-05 Rev. 04/00	ITT Industries Inc. AES – Reston
Request For Deviation / Waiver	
Waiver # DAS-W02, Rev. 1	Date 1 May 2002
VValver #	Date 1 May 2002
Deviation	Waiver 🗵
Originator	
Name:	Address: ITT Industries, Inc.
ITT Industries, Inc	1761 Business Center Drive
	Reston, VA 20190
Title Of Deviation / Waiver: DAS DMU Bi-Phase Service Above 75 kbps	
Contract Number: GS-35-0109J, Order # S 87	7070-Y, Task 11 Cage Code: 9M715
Classification: Minor 🛛	Major Critical
Part Number: 021-147012 / 021-147010 Title: DAS De	modulator Model 6002
Effectivity: All DAS pre-production and production DMU	s Recurring Deviation/ Waiver: Yes. No 🖂
Effect on Cost: None, if approved	Effect on Schedule: None, if approved
Effect on Logistics Support, Interface or Software: None, if approved	
Reference Documents: SRD Paragraphs:	
3.2.4.2.1.1.h — " support a return link signal with a Symbol Format Blf-L"	
3.2.4.2.1.1.k — " support a total return signal with a Data Rate Restriction of 1–300 kbps."	
3.2.4.2.1.1.I — " support a returnI CHANNEL data rate of 1–150 kbps. " 3.2.4.2.1.1.m — " support a returnQ CHANNEL data rate of 1–150 kbps."	
Description of Deviation / Waiver:	
Waive Bi-Phase services above 75 kbps. Limit services above 75 kbps to NRZ Symbol Format.	
Need for Deviation / Waiver:	
DAS will not meet not meet the Blφ-L specification for data rates above 75 kbps without a costly and major re-design.	
DAS uses a PNMF that provides parallel processing for rapid acquisition—the same PNMF for tracking in which the	
PNMF efficiently provides 'early', 'late' and 'on-time' PN correlations from a single path. Symbol timing is achieved by	
adjusting the PN chips summation that comprises a symbol. As the data rate increases, the number of PN chips per	
symbol decreases (e.g., 10 chips per symbol @ 300 kilo-baud—75 kbps bi-phase) which in turn decreases the resolution	
at which symbol timing adjustments can be made. This decrease in timing resolution results in degraded symbol tracking	
performance and leads to an effective SNR degradation.	
Corrective action taken:	
None. This model DMU will not meet this requirement. A new model will have to be developed.	

Submitting Activity Signature: Name: Title: Date: Walter E. Kearns ITT – AES, DAS PM 10 May 2002 **Customer Approval / Disapproval Approval** Disapproval Date: Name: Title: Signature:

2001 1 of 1 das-w02(rev1).doc